Primus

What's New

version 4.2.1

Auditdata

Table of Contents

1 Introduction

This document aims to provide an overview of the Primus 4.2.1 hotfix. While the hotfix is not mandatory, it is always recommended to run the latest available software on your system.

2 Updates in this release

Bug Fix: Automatic Recognition for New Transducers

This bug fix addresses an issue that occurs when switching transducers while the hardware is connected and powered up, but the Primus software is not running. In these cases, the calibration data stored in the transducer plug will not be read properly. The 4.2.1 hotfix ensures that the system reads and verifies calibration data under all circumstances. Therefore, it is highly recommended to update to this hotfix.

You can verify that your connected transducers have been read correctly by the software. To do so, simply navigate to **Help > License Information** and click on the **Connected Devices** tab. Ensure that the serial numbers of the listed connected transducers match the printed serial numbers on the transducer labels.

cense information	n				-		×
Location Info	License	es Connecter	d Devices				
Connected Device	s						
Serial Number		Device					
20131112		PFU+					
8		ніт					
Calibrations							
Calibrations Serial Number	•	Туре	Last Calibration	Next Calibration	Activation Date	Status	
Calibrations Serial Number 12345678	A	Type TDH-39	Last Calibration 08/02/2024	Next Calibration 08/02/2025	Activation Date 08/02/2024	Status Calibrated	
Calibrations Serial Number 12345678 81000019		Type TDH-39 HIT Coupler	Last Calibration 08/02/2024 27/10/2023	Next Calibration 08/02/2025 27/10/2024	Activation Date 08/02/2024 27/10/2023	Status Calibrated Local Calibr	atio
Calibrations Serial Number 12345678 81000019 90000167	^	Type TDH-39 HIT Coupler HIT Referenc	Last Calibration 08/02/2024 27/10/2023 27/10/2023	Next Calibration 08/02/2025 27/10/2024 27/10/2024	Activation Date 08/02/2024 27/10/2023 27/10/2023	Status Calibrated Local Calibr Local Calibr	atio
Calibrations Serial Number 12345678 81000019 90000167	*	Type TDH-39 HIT Coupler HIT Referenc	Last Calibration 08/02/2024 27/10/2023 27/10/2023	Next Calibration 08/02/2025 27/10/2024 27/10/2024	Activation Date 08/02/2024 27/10/2023 27/10/2023	Status Calibrated Local Calibr Local Calibr	atio
Calibrations Serial Number 12345678 81000019 90000167	A	Type TDH-39 HIT Coupler HIT Referenc	Last Calibration 08/02/2024 27/10/2023 27/10/2023	Next Calibration 08/02/2025 27/10/2024 27/10/2024	Activation Date 08/02/2024 27/10/2023 27/10/2023	Status Calibrated Local Calibr Local Calibr	atio
Calibrations Serial Number 12345678 81000019 90000167	A	Type TDH-39 HIT Coupler HIT Referenc	Last Calibration 08/02/2024 27/10/2023 27/10/2023	Next Calibration 08/02/2025 27/10/2024 27/10/2024	Activation Date 08/02/2024 27/10/2023 27/10/2023	Status Calibrated Local Calibr	atio
Calibrations Serial Number 12345678 81000019 90000167	*	Type TDH-39 HIT Coupler HIT Referenc	Last Calibration 08/02/2024 27/10/2023 27/10/2023	Next Calibration 08/02/2025 27/10/2024 27/10/2024	Activation Date 08/02/2024 27/10/2023 27/10/2023	Status Calibrated Local Calibr Local Calibr	atic
Calibrations Serial Number 12345678 81000019 90000167		Type TDH-39 HIT Coupler HIT Referenc	Last Calibration 08/02/2024 27/10/2023 27/10/2023	Next Calibration 08/02/2025 27/10/2024 27/10/2024	Activation Date 08/02/2024 27/10/2023 27/10/2023	Status Calibrated Local Calibr Local Calibr	atio atio
Calibrations Serial Number 12345678 81000019 90000167	-	Type TDH-39 HIT Coupler HIT Referenc	Last Calibration 08/02/2024 27/10/2023 27/10/2023	Next Calibration 08/02/2025 27/10/2024 27/10/2024	Activation Date 08/02/2024 27/10/2023 27/10/2023	Status Calibrated Local Calibr Local Calibr	atio atio

If there is a mismatch between serial numbers, follow these steps to correct it:

1. In the Measure software, go to **Tools** > **Refresh Transducer Data**.



- 2. Select the required transducer and click **Refresh Transducer Data**.
- 3. The system will inform you once the process is finished. You can close the window and start using the system normally.

If you have encountered issues with transducers not being read properly, we recommend updating the software immediately. If any further support is required, please contact support@auditdata.com.

3 Hotfix Release Notes

Dependencies

Primus 4.2.1 supports NOAH version 4 or higher. To use the Primus Panel under Auditbase System, Auditbase version 4.17.01 or higher is required.

Installation

Upgrade to the latest version to benefit from all enhancements.

To upgrade your Primus to version 4.2.1:

- 1. Run the set-up file: **Setup_Primus_4_2_1.exe**.
- 2. Follow the instructions on the screen.

4 Support

For any questions or assistance, please visit <u>www.auditdata.com/support</u>.