



DK-Taastrup, 13 November 2009

# AuditBase System Service Announcement

## **AuditBase 41404 Noah Hotfix (Delay param).**

### **Problem description:**

The NOAH Module selection window does not open. Noah client runs out of time to show them.

### **Solution description:**

The problem is related to dual core processor computers. Processes running simultaneous tasks instead of expected in sequence.

To solve this problem, installation of an AuditBase patch is required. The patch "setup.exe" is applicable for **AuditBase version 4.14.xx**.

The changes are described in the readme.txt file.  
Please download the files here:

[ftp://files.auditdata.com/General/AuditBase\\_41404\\_Noah\\_Hotfix\\_\(Delay\\_param\)](ftp://files.auditdata.com/General/AuditBase_41404_Noah_Hotfix_(Delay_param))

- Readme.txt
- Setup.exe (1,5 Mb)

OBS: If using the link directly does not work, please copy/paste the link to your browser.

### **Changes:**

Updated NOAH4AuditBase.exe for 4.14.04 (v.1.0.1.46; create date 04/03/2009)

### **Configuration:**

Audit.ini should be modified according to the readme file;

Add:

[NOAH]

KILLNOAHDelay=value in millisec (Ex: KillNOAHDelay=1000)

Default delay value (if not set in audit.ini) is 500 ms.

Try out different setting greater than 500 ms until the problem no longer appears.

## **FTP login details**

<ftp://files.auditdata.com/General>

ID: auditbase

Password: system4

## **Contact details**

In case of problems downloading the files, please contact Auditdata Customer Support:

### **Denmark**

Phone 70 20 31 24 (dial 1)

[dksupport@auditdata.com](mailto:dksupport@auditdata.com)

### **UK**

Phone 8707 345240

[uksupport@auditdata.com](mailto:uksupport@auditdata.com)